

# Muller Honda - Severe Maintenance Schedule:

2002-2004 Odyssey • 2002-2005 Pilot V6 • 2002-2005 Accord V6

Recommended Maintenance	3750	7500	15K	22K	30K	45K	60K	75K	90K	105K	120K
Perform 19 Point Inspection	X	X	X	X	X	X	X	X	X	X	X
Change Engine Oil And Filter	X	X	X	X	X	X	X	X	X	X	X
Inspect and top-off fluid levels	X	X	X	X	X	X	X	X	X	X	X
Inspect : Exhaust/Suspension	X	X	X	X	X	X	X	X	X	X	X
Inspect: Tires/Adjust Pressure	X	X	X	X	X	X	X	X	X	X	X
Perform Tire Rotation		X	X	X	X	X	X	X	X	X	X
Front/Rear Brake Service		X	X	X	X	X	X	X	X	X	X
Change Rear Differential Fluid (Pilot)			X		X	X	X	X	X	X	X
Replace Engine Air Filter		X	X		X	X	X	X	X	X	X
Change Trans Fluid					X		X		X		X
Replace H.E.P.A. (Cabin) Filter					X		X		X		X
Check Engine Valves for noise			X		X	X	X	X	X		X
Replace Platinum Spark Plugs										X	
Perform V6 Valve Adjustment										X	
<b>Replace Timing Belt, Water Pump, Tensioner and Drive Belts</b>										X	
Replace Engine Coolant											X
<b>Replace Engine Coolant at 120K Miles, then Every 60K. Replace Brake Fluid Every 3 Years, Regardless of Mileage</b>											

**For Pricing, Appointments or More Information Call 847 • 831 • 4200**